

Time Sync

Release Notes

A-TSM

Document No. D107-011

Document Revision 1.0

04/2018

Firmware Revision 1.014

CONTENTS

1. Preface.....	2
1.1. Compatibility.....	2
1.2. Notes.....	2
1.3. Additional Information.....	2
1.4. Support.....	3
2. Improvements.....	3
3. Anomalies Fixed.....	4
4. Known Anomalies.....	4



1. PREFACE

1.1. COMPATIBILITY

Firmware revision 1.014 of the Time Sync module will require the following compatible versions:

Software	Version
Slate	1.036 and later

1.2. NOTES

The following should be noted:

- Firmware upgrades will be done using Aparian's Slate software.
- Aparian flash files have an *.afb* extension.
- Slate can also be used to set the initial network parameters using its DHCP server.
- Should any interruptions cause the module to not complete the firmware upgrade the module will return to Safe Mode. The user can then re-flash the module with the application firmware. See the user manual for more information regarding Safe Mode.

1.3. ADDITIONAL INFORMATION

The following resources contain additional information that can assist the user with the module installation and operation.

Resource	Link
Slate Installation	http://www.aparian.com/software/slate
Time Sync User Manual Time Sync Datasheet Example Code & UDTs	http://www.aparian.com/products/timesync
Ethernet wiring standard	www.cisco.com/c/en/us/td/docs/video/cds/cde/cde205_220_420/installation/guide/cde205_220_420_hig/Connectors.html
GPS information	https://www.u-blox.com/images/stories/the_gps_dictionary.pdf
1588 Precision Time Protocol (PTP)	http://www.ieee1588.com/
Network Time Protocol (NTP)	http://www.ntp.org/documentation.html

CIPSync	https://www.odva.org/Home/ODVATECHNOLOGIES/CIP/CIPTechnologyOverview/CIPSync.aspx
---------	---

1.4. SUPPORT

Technical support will be provided via the Web (in the form of user manuals, FAQ, datasheets etc.) to assist with installation, operation, and diagnostics.

For additional support the user can use either of the following:

Contact Us web link	www.aparian.com/contact-us
Support email	support@aparian.com

2. IMPROVEMENTS

The following updates are included in this firmware revision.

Revision	Improvement	Description
1.014	PTP over IEEE802.3	Support for PTPv2 network transport IEEE802.3
1.013	NTP Source	Support for NTP time source.
1.012	1588 PTP Holdover Support	Added support for 1588 PTP holdover reporting.
1.011	Peer-to-Peer Delay Mechanism	Added support for 1588 PTP Peer-to-Peer (P2P) delay mechanism
1.009	PTP TTL	Add ability to configure TTL for 1588 PTP packets
	Modbus	Add ability to set time in a Modbus Register
	SLC	Add ability to set time in SLC
	PLC5	Add ability to set time in PLC5
1.008	EtherNet/IP	Updates to EtherNet/IP and CIP communication to comply with latest ODVA certification.
	Class 1 Connection	Improved stability when running at lowest RPI (1ms).
1.006	EtherNet/IP	Minor improvements to communication stability.
1.005	PTP	Minor PTP data exchange improvements
1.003	Ethernet Cable Length	Added Ethernet cable length measurement
	Reset	Fix CIP reset anomaly
	Owned	Fixed owned indication when receiving a Forward Close.
1.002	Requested Packet Interval (RPI)	Minimum RPI was changed to 1ms from 10ms

3. ANOMALIES FIXED

The following anomalies have been fixed in this firmware revision.

Revision	Anomaly	Description
1.014	None	-
1.011	Second Rollback	Fix anomaly that could occur when a PTP delay request is received at the edge of a second rollover causing the timestamp second to rollback one second.
	PTP Domain	Fixed operation of PTP Domain to not process packets from a different domain.
	PCCC Connection	Fixed PCCC connection timeout when connection to remote PLC/SLC/MicroLogix is lost
	PTP Enable	Fixed anomaly that could cause the PTP to be disabled when changing PTP parameter from Time Sync Object
1.010	Remote Device	Fix anomaly where if PTP was disabled and a remote device is used then the base time would not update.
1.009	Ethernet	Fix for certain broadcast Ethernet packets that were being re-broadcasted.
1.007	Other	Minor bug fixes
1.006	Time Rollover	Fix issue where PTP delay request is close to rollover causing the timestamp to be out by a second.
1.004	ARP client list	Fix issue where DHCP requests increase client list count

4. KNOWN ANOMALIES

The following known anomalies exist in this firmware revision.

Revision	Anomaly	Description
1.014	None	-